

Fix Intel Gigabit Card 82574L Missing from CentOS

Install EI Repo

```
yum install nano kmod-e1000e && sudo nano /etc/modprobe.conf && reboot
```

[Need to download the RPM?](#) I realize now that in my first trial, I had one nic missing, but another that worked, but installing via YUM is hard without internet, what I did the second time I ran into this was create an ISO then load that into VM and mount it and install drivers....

Replace

```
#alias eth0 e1000e  
alias eth0 kmod-e1000e
```